

19

2300Z

03-08-1984

PAGE 01

ADD ADS CHR SM SMT SMT2 SMD STE AP  
AGR18/11/33-18/2/46-18/11/13-18/3/33XX ADA

VZCZCKAA903IPC5792

RR

DE #8081 2150016

ZNY MMNSH

ZKZK RR XDD DE

R 020016Z AUG 84

FM AUSLO

TO DSD

AUSLO

ZEM

~~CONFIDENTIAL~~

AD-1211-84

MARSIK TERMINALS

REF A: MY AD-1187-84, 272110 JUL

B: MY AD-1240-84, 282109 SEP 83

CRAY ADVISE THAT THEY HAVE BEEN IN CONTACT WITH THE RAYTHEON PEOPLE WHO IN TURN ADVISE THAT THEY KNOW OF NO REASON WHY THE TERMINALS SHOULD NOT OPERATE AT 50HZ. THERE WOULD BE SOME CHANGE OF STRAPPING AT THE BACK OF THE TERMINAL TO TAKE CARE OF THE CHANGE OF THE POWER SUPPLY BUT THAT IS ALL.

2.. IN THE LIGHT OF THIS INFO AND THAT PROVIDED IN REF B ET AL, AND WITH YOU NOW ABOUT TO RECEIVE THE MANUAL SUGGEST THERE IS LITTLE MORE THAT WE CAN DO EVEN THOUGH WE STILL HAVE ONE MORE RESPONSE TO COME IN

#8081  
NNNN