

P 260040Z

260040

FILE 31 9 118 33

FM AUM 352

TO ARMY CANBERRA

ZEM

6

AD (D)

AD (U)

~~SECRET~~ COMINT CHANNELS SIGS 103/68.

FOR M18.

YOUR 120050Z. ARDF REPORT FROM 1 NOV 67 TO 31 JAN 68 INCL.

1. TOTAL FIXES 266.

GRADINGS GOOD 52, FAIR 153, POOR 39, CUTS 22,

TOTAL FLYING TIME - 288 HOURS



2. SUGGESTED IMPROVEMENTS TO EQUIPMENT.

A. A FACILITY TO SWITCH TO EITHER ANTENNA AT ANYTIME. REASON: AUDIO NULL FOR AURAL FIX.

B. FLEXIBLE LIGHT TO BE FIXED TO TOP OF EQUIPMENT FRAME. REASON: OPERATIONS NIGHT FLYING LIGHT.

C. TELESCOPIC LIGHT SHADE FITTED TO SCOPE WITH RUBBER PROTECTION FOR THE FACE. REASON: TO OVERCOME REFRACTIVE ERROR,

THE CRO HOOD CARDBOARD (LP) IS NOT SUITABLE,

D. DEVICE TO LOCK. ANTENNA ASSEMBLY AND MAIN EQUIPMENT FRAME TO AIRCRAFT SEAT RAILS BE CONSTRUCTED OF MATERIAL OTHER THAN ALUMINIUM.

REASON: THREAD OF ALUMINIUM LOCKING DEVICE TENDS TO CROSS THREAD AND STRIP.