Declassified by ASD 21/4/2021 Information removed for national security and/ or personal sensitivities

NNNQDAØ81

DE

802 3510920

P 170830Z

FM AUM 352

TO ARMY CANBERRA

INFO

DSD

ZEM

SIGS 569.

FOR MIS. ARDF REPORT NO. 20.

1. ARDF

A. PERIOD OF REPORT 1-15 DEC INCL

B. FLYING TIME DAY 52 HOURS

HOURS NIGHT 8 HORR C. RESULTS 32 LIVE TIRGET FIXES

- D. CLASSIFICATIONS: GOOD 2, FAIR 24, POOR 4, CUTS 2.
- E. GENERAL: NO FLYING IN MR6 DURING PERIOD OF REPORT AS REACTIVATION OF INTEREST IN 1 ATF AREA.
- 2. EQUIPMENT.

FROM 1-3 DEC NO FLYING DUE TO TWO FAULTY RZ17 RECEIVERS. ONE REPAIRED

FILE 118 181 Ap(c) (cr) 0 P

Multi

OAR 31/9/18

BY TAKING 3RD MIXER STAGE MODULE FROM OTHER SET WHICH STILL HAS.

DIFFICULT TO LOCATE INTERMITTENT FAULT. THIS SET AT PRESENT WITH

RAEME WHO STATE IT CANNOT BE REPAIRED IN THEATRE. ISSUED AND

REPLACEMENT SET URGENTLY REQUIRED. AS WHOLE ARDF EFFORT RELIES ON TWO

RECEIVERS AT PRESENT IN EQUIPMNT: INDENT NO RM 1/67 SUBMITTED TODAY

TO