SMO?

| DSD | FILE |                | FOLIO  |
|-----|------|----------------|--|
| 18  | 11   | 2              | 3/   |
|     | /    | Annual Control | and the same of th |

5732Z 17-56-1985 PAGE 51

AMO(R)-18/11/2 SM AP SMO SMT

VZCZCR8A778

TO CRAY RESEARCH (UK) LTD (51-848841)

BT

ATTENTION

AS PER YOUR DRAWING NO UP4014 REV. A DATED 18-2-85 ITEM NO 15 FOR THE IOC WAS SUPPOSED TO BE MODIFIED. THIS HAS NOT BEEN DONE AND IT IS THE SAME AS THE OTHER ITEMS 15 SHOWN ON THE DRAWING. WE BELIEVE THAT IT IS JUST A MATTER OF TURNING THE OUTLETS 180 DEGREES IN RELATION TO THE INLET SO THAT THEY FACE THE OPPOSITE WAY TO THE INLET.

THE INSTALLATION OF THE PIPING IS ALMOST COMPLETE SO IF YOU CAN CONFIRM THE ABOVE ASAP THE MODIFICATION CAN BE CARRIED OUT ON SITE. AT OUR MEETING ON 22 MAY 1985 WE WERE PROMISED NEW DRAWINGS FOR THE MACHINE UNIT SPECIFICATIONS AND THE POWER DISTRIBUTION. THESE HAVE NOT YET ARRIVED. COULD YOU PLEASE ASCERTAIN THEIR STATUS.

Declassified by ASD - 04/02/2022 Information removed for national security and/or personal sensitivities