

3101
DP → *DP1* → *DP2* → *DP* 46.
→ AGR 27/4/6

J001 0531Z 26-06-1984 PAGE 01

OP SE ADS AGR-27/4/6
VZCZCR9A317
RR
DE #1136 1780331
ZNY MMNSH

Ref Para 2B.

DP
Please see attached.

R 260330Z JUN 84
FM DSD
TO DEFNAV CANBERRA
ZEM

Pleasey man
said that attached package is
could be provided at a
cost of about \$5.64k FOB.
SER estimates ± \$1200 for
turnkey.

↳ Multicouplers and
Programs

~~SECRET~~

OP025-84
DEFNAV FOR DDNI INFO DNCD, DFEP
PUSHER AT SHOAL BAY

DP1.

1. THE PUSHER AT SHOAL BAY IS NEARLY TEN YEARS OLD. BELIEVE THAT IT IS NOW TIME TO ASSESS ITS CONDITION AND REMAINING COST EFFECTIVE LIFE.
2. APART FROM THE POSSIBLE NEED TO PROGRAM FUNDS FOR REFURBISHMENT/REPLACEMENT, THE FOLLOWING RELATE:
 - (A) A DSD TASK, WHICH IS TO BE REVISED, ON DRCS CONCERNS NEXT GENERATION HF AERIALS AN EARLY END-OF-LIFE DATE FOR THE SHOAL BAY PUSHER COULD EFFECT PRIORITY GIVEN TO THIS TASK.
 - (B) A REPLACEMENT DATE MAY AFFECT THE UNRESOLVED QUESTION OF A NORLIN PRE-AMPS REPLACEMENT,
 - (C) THERE IS THE QUESTION OF WHETHER THE GONIO (WHICH HAS, SO FAR, GIVEN EXCELLENT SERVICE) SHOULD BE REPLACED WITH A SOLID STATE VERSION (EXPECTED TO BE AVAILABLE WITHIN, SAY, TWO YEARS), AND
 - (D) VULNERABILITY CONSIDERATIONS MAY FAVOUR REFURBISHMENT ON PRESENT SITE, OR REPLACEMENT ON A NEW SITE DEPENDING ON ASSUMPTIONS ADOPTED.
3. CAN NAVY THEREFORE UNDERTAKE TO MAKE THE APPROPRIATE STUDIES/ENQUIRIES WITH A VIEW TO DETERMINING REALISTIC REFURBISHMENT REQUIREMENTS (IF ANY) AND TO FORECAST AN END-OF-LIFE

RED

J001 0531Z 26-06-1984 PAGE 02

DATE FOR THIS PUSHER. IF THIS CAN BE DONE, WHEN MIGHT THIS ADVICE BE FURNISHED?
#1136