

## SECRET

125/39

11th October, 1958

To:- Security Liaison Officer, Federation of Malaya.

Subject:- INSPECTION REPORT OF CAPTURED ENEMY WIRELESS EQUIPMENT.

Herewith report in accordance with para. 14 of Director of Operations Instruction No. 22

## PART I - WIRELESS SETS

- (A) Philips Broadcast receiver 3 W/Band, one medium and 2 S/Wave bands. Contained in KD case. Marked with letter P.
- (B) Semi Portable.
- (C) Philips No. L26319.
- (D) Any Type.
- (E) Red dots on dial at approx 1200 Kcs, 1100 Kcs, 5 Mcs, 16 Mcs, 14 Mcs, and 8 Mcs.
- (F) Holland.
- (G) Battery.
- (H) 1.5 filament and 90V H.T.
- (J) N.A.
- (K) N.A.
- (L) N.A.
- (M) (a) No. Badly damaged condition.(b) No. See para. "S".
- (N) Miniature Standard B7G Base. receiving Valves.
- (P) A. 1500 600 Kes, 6 3 Mes, 20 8 Mes.
- (Q) No.
- (R) None
- (S) This set though obviously not used as a broadcast set for some time has been modified for an unknown purpose. The modifications comprise of the installation of a transformer (due to damage, possibly in transit) purpose unknown.

An additional twin sockets marked "A & E" and a standard miniature 4 pin socket have also been fitted.

Recovered with this equipment was a small K.D. haversack marked with the letter "P" which contained a small metal case containing a one Valve (type DL 94) - tunable circuit.



## SECRET

- 2 -

This apparatus terminates on a 4 pin jack which fits the 4 pin socket previously referred to. A second small metal box recovered simultaneously with the above mentioned equipment, contains a variable condenser, terminating red and a black wander plugs, which fit into sockets marked "A & E".

The standard of workmanship and apparent technical ability are fairly good.

It is regretted that limited facilities do not allow a more detailed report as to the purpose of the modifications.

(Signed)

FORCE SIGNALS OFFICER