Ref : SMO/20/86

Declassified by ASD - 03/02/2022 Information removed for national security and/or personal sensitivities

CRAY PERIPHERAL CUTOUTS

AP APG

Through SM SMT

Please arrange for the following cutouts to be made in room 1-68 which are to allow for the orderly installation of Cray Peripheral equipment.

Cutouts required 2 x TBL1

1 x TBLZ

1 x MCG3 (MMCU)

2 x LP3

2 x PECZ

6 x DD49

2 x NSC

2 x PTS

The cutout sizes required for the NSC's and PTS's are to be supplied by of Techway.

We also require two more power outlets for the two PTS's.

Attached are copies of each of the floor cutout diagrams.

A/SMO

12 February 1986