

OZZCZCLRA515

R

30

2

2

34.

PP

DE 165 05/0545Z OCT.

P 050540Z

FM

TO /D OF C CANBERRA

INFO DSD

ZEM

Declassified by ASD - 02/08/2022
Information removed for national
security and/or personal sensitivities

~~CONFIDENTIAL PASS BY COMINT CHANNELS~~

IN ORDER TO MAINTAIN CONTINUITY OF COVER PRESENT TASKING REQUIRES
TWO CIRCUITS TO BE TAPE RECORDED DURING THE LUNCH BREAK, WHILE
NUMBER OF OPERATORS IS REDUCED.

2. PRESENT TPR-1 POSITION IS SUCH, THAT OF TWO MACHINES HELD, ONE
IS NOT BAD BUT THE OTHER REQUIRES A MAJOR OVERHAUL. IS
REQUESTED TO INDICATE WHETHER THEIR E.M.I. TWIN TRACK RECORDER IS BEING
USED OPERATIONALLY BECAUSE IT WOULD BE INVALUABLE HERE

3. SUBJECT TO NOT REQUIRING THE RECORDER, D OF C IS
REQUESTED TO INITIATE SIGNAL ACTION TO TRANSFER TO THISTA BY AIR
FREIGHT

4. ACTION WILL BE TAKEN BY THISTA TO DEMAND TWO SERVICEABLE
TPR-1 RECORDERS OR MORE MODERN TWIN TRACK REPLACEMENTS TO ENABLE
PRESENT MACHINES TO BE RETURNED

130 130

NNNN