VV MGA679 HH

26 2 54 48

RR

DE

240 2201058

ZNY RRRRR

R Ø81Ø54Z AUG 75

ADE OFR DP CAAR

FM NOCNA

TO /DEFNAV CANBERRA

INFO ZEN/HMAS COONAWARRA

26/2/54

/GOSIEAA

DSD MELBOURNE

BT

RESTRICTED

SIG CWD

SHOAL BAY PROJECT - PROGRESS AT Ø7 AUG 75

- A. NOCNA CWD Ø1Ø537Z AUG 75
- B. DEFNAV CANBERRRA CWD Ø1Ø647Z AUG 75
- 1. PLESSSY
 - A. FOLLOWING ITEMS OUTSTANDING
 - 1. REPAIR VECTOR VOLTMETER
- 2. REPAIR BF HUNT INTERCOM. UNIT NOW U/S ONE WAY. AWAITING SPARE AND SERVICING DATA.
- 3. SYSTEM DRAWINGS AND HANDBOOKS NOT YET ON SITE. PRELIMINARY
 AS FITTED DUCTING DIAGRAM NOT YET PRODUCED
 - 4. RECTIFICATION INTERMOD INTERACTION BETWEEN PV562S AND

MULTICOUPLERS

Declassified by ASD - 10/05/2022 Information removed for national security and/or personal sensitivities

- 5. MECHANICAL INSTALLATION AND MODIFICATION PUREGAS ALARMPANEL.
- 6. REPAIR ONE AIKEN MULTICOUPLER
- 7. REMOTE INDICATION OF 30V POWER SUPPLY IN BF HUT DEFECTIVE
- B. OVERALL SYSTEM NOISE TEST NOT YET COMPLETE
- C. PV562S NOT YET RECONFIGURED
- D. STATES THAT ITEMS A(2), A(4), A(5), B AND C ABOVE
 WILL BE COMPLETE 11 AUG 75. ON SITE TEAM DOES NOT SHARE PLESSEYS
 OPTIMISM. RECOMMEND DNCD REP VISIT SITE FOR RECOMMENCEMENT
 ACCEPTANCE TESTING 18 AUG 75
- E. STATES SYSTEM WILL BE READY FOR INSPECTION

 AUDIT 11 AUG 75. SOME DOCUMENTATION IS STILL OUTSTANDING

 INCLUDING CONCESSION NOTES
- 2. RACAL
- A. RACAL REP STATES ALL CONSOLES NOW CLEARED OF DEFICIENCIES

 AS FAR AS MATERIALS WILL ALLOW
 - B. FOLLOWING MATERIALS AWAITED
 - 1. INTERCOM SPACERS
 - 2. CLOCK LEVERS
 - 3. CABINET SUPPORT BRACKETS
 - 4. IDENTIFICATION LABELS FOR CABINET WIRING

PAGE 3 240 RESTRICTED

- C. DELIVERY ITEMS B(1) AND B(2) EXPECTED 11 AUG 75
- D. ALL OPS CONSOLES NOW ELECTRICALLY TESTED
- 3. CONSTRUCTION

RETEST SCREENED ROOM COMPLETED, SATISFACTORY

BT